**By two weeks progress**

| Identified Issues | Corrective Actions | | Assumption or Risks |
|---|---|---|---|
| | Actions Taken | Actions to be Taken | |
| column finishing levels for roof beams not received | Informed consultant | | Affected the construction of roof beams of wing 01 |
| Lintol levels cannot be taken due to structural beams | Informed consultants site reprecentative | Inform by a RFI | The opening sizes will bw reduced if maintain the given sill levels. |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |